

-
- Exploded view diagram of the power supply unit showing the following components and quantities:
- 3x Screws
 - 3x Nut
 - 3x Washer
 - 1x 20 Amp. minifuse
 - 1x 15 Amp. minifuse
 - 2x Fuse holder
 - 1x Fuse holder cover
 - 1x Fan
 - 10x Fan screws
 - 4x Fan mounting brackets
 - 1x Fan connector
 - 1x Fan connector plug
 - 1x Fan connector plug
 - 1x Fan connector plug
 - 1x Fan connector plug

														
7 PIN	1/L	2	-	3/31	4/R	5/58-R	6/54	7/58-L	X	X	X	-	X	-
13 PIN	1/L	2	-	3/31	4/R	5/58-R	6/54	7/58-L	8	9	10	11	-	13
Pmax	21W	21W	-	X	21W	42W	3x21W	42W	21W	180W/15Amp	Option	-	-	-
ISO	YE	BU	-	WH	GN	BN	RD	BK	PI	OG	GY	WH/BK	-	WH/RD

